

**Flood Control Project Maintenance
Levee Inspections**

2010 Channel Summary Report

Overall Unit and Item Ratings

Madera County FCWCA

Ash Slough

Overall Unit Rating	Rated Item	Item Rating
N	Channel Not Rated	

Berenda Slough

Overall Unit Rating	Rated Item	Item Rating
N	Channel Not Rated	

Chowchilla River

Overall Unit Rating	Rated Item	Item Rating
N	Channel Not Rated	

Fresno River

Overall Unit Rating	Rated Item	Item Rating
N	Channel Not Rated	

Flood Control Project Maintenance**Unit Cover Sheet****2010 Channel Inspection Results****Madera County FCWCA**

Channel
Ash Slough

Channel Rating	N
Date of Inspection	n/a
DWR Inspector	Herman Phillips
Accompanied By	

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2010

Madera County FCWCA

Channel	Channel Length	Inspection Start/End	Inspector
Ash Slough	19.00	n/a	Herman Phillips

LMR No.	Check Point	View	Item	* Location	** Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
1	Low Water Crossing	Up	Vegetation & Obstructions		N	Inspector Comments: Due to resourcing challenges, this channel did not have inspections completed this year.	° °		1

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

Flood Control Project Maintenance**Unit Cover Sheet****2010 Channel Inspection Results****Madera County FCWCA**

Channel
Berenda Slough

Channel Rating	N
Date of Inspection	n/a
DWR Inspector	Herman Phillips
Accompanied By	

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2010

Madera County FCWCA

Channel	Channel Length	Inspection Start/End	Inspector
Berenda Slough	18.00	n/a	Herman Phillips

LMR No.	Check Point	View	Item	* Location	** Rating	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
1	Santa Fe Dr	Up	Vegetation & Obstructions		N	Inspector Comments: Due to resourcing challenges, this channel did not have inspections completed this year.	37.143420 ° -120.162110 °		1

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

Flood Control Project Maintenance**Unit Cover Sheet****2010 Channel Inspection Results****Madera County FCWCA**

Channel
Chowchilla River

Channel Rating	N
Date of Inspection	n/a
DWR Inspector	Herman Phillips
Accompanied By	

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2010

Madera County FCWCA

Channel	Channel Length	Inspection Start/End	Inspector
Chowchilla River	28.00	n/a	Herman Phillips

LMR No.	Check Point	View	Item	Location *	Rating **	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
1	Downstream Buchanan Dam	Up	Vegetation & Obstructions		N	Inspector Comments: Due to resourcing challenges, this channel did not have inspections completed this year.	° °		1

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

Flood Control Project Maintenance**Unit Cover Sheet****2010 Channel Inspection Results****Madera County FCWCA**

Channel
Fresno River

Channel Rating	N
Date of Inspection	n/a
DWR Inspector	Herman Phillips
Accompanied By	

**Flood Control Project Maintenance
Channel Inspections**

Channel Inspection Report By Check Point and View Direction - 2010

Madera County FCWCA

Channel	Channel Length	Inspection Start/End	Inspector
Fresno River	13.00	n/a	Herman Phillips

LMR No.	Check Point	View	Item	Location *	Rating **	Inspector Comment	GPS Latitude & Longitude	Photo	Issue No
1	U/S Limit @ Hidden Dam, Daulton Dr.	Up	Vegetation & Obstructions		N	Inspector Comments: Due to resourcing challenges, this channel did not have inspections completed this year.	37.103916 ° -119.888060 °		1

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected